



# Information Bulletin

03.02.2023 Update

We are pleased to share that Winstone Wallboards GIB<sup>®</sup> Plasterboard manufacturing and distribution facilities have not been affected by the recent weather events in Auckland, allowing us to continue regular supply to the market.

While we navigate the ongoing interruptions of recent Auckland weather events, we appreciate your patience, and reinforce that we are here to help as best we can in these circumstances.

Like you Winstone Wallboards is unable to predict the full extent of the possible industry disruption resulting from these events, however we will continue to support our customers as much as possible with technical support, guidance and product supply.

Winstone Wallboards is aiming to provide timely market updates as appropriate. Updates will be posted on the GIB<sup>®</sup> website, please refer to [www.gib.co.nz](http://www.gib.co.nz) for the latest information.

Should you become aware of any potential delays occurring on your site from the recent weather events please contact your merchant to review your scheduled GIB<sup>®</sup> plasterboard delivery.

With recent widespread flooding there will be many houses that need correct assessment of the damage and how to remediate that damage. The below articles are designed for all instances of flooding, with the Auckland flooding event we suggest this water is classified as 'contaminated' and all plasterboard be replaced as outlined in [GIB<sup>®</sup> Best Practice Series: Replacing Water Damaged Board](#).

We have a team of Technical Advisors available to help with any further information - please call the GIB<sup>®</sup> helpline on 0800 100 442.

## PDF Resources

---

[GIB<sup>®</sup> Best Practice Series: Assessment of Water Damaged Board](#)

[GIB<sup>®</sup> Best Practice Series: Replacing Water Damaged Board](#)